

Yamaha Steinberg USB Driver V1.5.2 for Mac Release Notes

Contents

[System Requirements for Software](#)

[Main Revisions and Enhancements](#)

[Legacy Updates](#)

System Requirements for Software

NOTE

Note that the system requirements may be slightly different from those described below depending on the particular operating system.

OS	Mac OS X 10.5.8/Mac OS X 10.6.x/Mac OS X 10.7
CPU	Intel processor (Intel Core Duo CPU recommended)
Memory	1GB or more
Interface	Equipped with a USB connector
Hard Disk	Free disk space of 50MB or more; high-speed hard disk

Main Revisions and Enhancements

V1.5.1 to V1.5.2

- Now supports Mac OS X 10.7.
- Improved audio input and output performance.
- Solved the problem in which applications such as DAW software might not work because the lead-off data would not be sent/received properly after second launching of the applications on Mac OS X 10.6.8 or later (Mac OS X 10.6.7 or later on Mac with Thunderbolt port).

V1.5.0 to V1.5.1

- Now supports Steinberg UR824.
- Solved some minor problems.

NOTE

Yamaha Steinberg USB Driver V1.5.1 is the version which is included in the TOOLS for UR824 CD-ROM (labeled "YD307A0") in the Steinberg UR824 package.

V1.3.0 to V1.5.0

- Now supports Steinberg UR28M.
- Solved some minor problems.

NOTE

Yamaha Steinberg USB Driver V1.5.0 is the version which is included in the TOOLS for UR28M CD-ROM (labeled "YD304A0") in the Steinberg UR28M package.

Legacy Updates

V1.2.0 to V1.3.0

- Now supports Yamaha MOX6/8.
- Solved the problem in which noise would occasionally occur during playback in a specific condition when using a device compatible with the Yamaha Steinberg USB Driver on Mac computer with an Intel processor and Mac OS X 10.6.5 or later.

V1.1.1 to V1.2.0

- Now supports 64-bit kernel of Mac OS X 10.6.
- Changed the system requirements to the following.
 - Mac OS X 10.5.8 or 10.6.x
 - Mac computer with an Intel processor

For details, refer to the "[System Requirements for Software.](#)"

- Solved the problem in which noise would occasionally occur during playback when using a device compatible with the Yamaha Steinberg USB Driver on Mac computer with an Intel processor and Mac OS X 10.6.5 or later.

V1.1.0 to V1.1.1

- Improved the stability of Yamaha Steinberg USB Driver on a Mac with an Intel Core i series processor.
- Improved the following problems.
 - When using a device compatible with Yamaha Steinberg USB Driver on a Mac with an Intel Core i series processor, recorded audio data might be briefly interrupted.
 - When using a device compatible with Yamaha Steinberg USB Driver on a Mac with an Intel Core i series processor, noise may occasionally occur when playback starts.

V1.0.1 to V1.1.0

- Now supports Steinberg CI1 and Steinberg CI2+.

V1.0.0 to V1.0.1

- Yamaha Steinberg USB Driver now supports Mac OS X 10.6.

Company and product names that appear in this document are the trademarks or registered trademarks of their respective companies.

(C) 2010-2011 Yamaha Corporation All Rights Reserved.